

WORK VEHICLE WITH FLASHING AMBER WARNING BEACON

2. RADIO CONTACT BETWEEN WORK CREW AND SHADOW VEHICLE REQUIRED.

3. PCMS RECOMMENDED.

SHADOW VEHICLE WITH FLASHING AMBER WARNING BEACON (TMA RECOMMENDED, BUT NOT REQUIRED)